



VGB 2008 SUCTION OUTLET RETROFIT CROSS-REFERENCE CHART

Replace suction outlet covers five years after installation with AquaStar anti-entrapment suction outlet covers.
CPSC-approved • ANSI/APSP-16 2011 • NSF 50-2009

EXISTING PART #*	REPLACEMENT VGB PART #*	EXISTING PART #*	REPLACEMENT VGB PART #*
4RNDxxx, R4RNDxxx (4" Round)	6HPHAxxx and SCW1026	12xxx, 12MFxxx, P12xxx, SRFS12xxx SUN12xxx, SUN12WRxxx, WAV12xxx, WAV12WRxxx (12" Square)	1216xxx, 12MFxxx, WAV12WRxxx
6HPxxx, 6HPHAxxx (6" Round)	6HPHAxxx	R12MFxxx, RFS12xxx, RWAV12xxx, RSUN12xxx (12" Square)	1216xxx, R12MFxxx
8AVxxx, 8HPxxx, 8AVWRxxx, 8CCxxx, 8FLxxx, 8FUWxxx, 8MFxxx, A8xxx, A8Rxxx, LP8AVxxx, LP8AVWRxxx (8" Round)	8MFxxx, A8Rxxx, LP8AVWRxxx	914xxx, R914xxx (14" Square)	914xxx
R8MFxxx, R8HPxxx, RLP8AVxxx (8" Round)	R8MFxxx, A10RCFRxxx	1216xxx, R1216xxx (16" Square)	1216xxx
9xxx, P9xxx, SRFS9xxx, SUN9xxx, SUN9WRxxx, WAV9xxx, WAV9WRxxx (9" Square)	914xxx, 9MFxxx, WAV9WRxxx,	18xxx, P18xxx, SUN18xxx, SUN18HPHxxx, SUNA18xxx, SUNA18WRxxx, WAV18xxx, WAV18WRxxx (18" Square with Four 9" Squares)	18MFNFxxx, P18NFxxx, RSUN18HPHxxx, WAV18WRNFxxx
LPRFS9xxx, RFS9xxx, RSUN9xxx, RWAV9xxx (9" Square)	914xxx, R9MFxxx	24xxx, P24xxx, WAV24xxx (24" Square with Four 12" Squares)	24NFxxx, WAV24NFxxx
10AVxxx, 10AVRxxx, 10AVWRxxx, 10CCxxx, 10FLxxx, 10MFxxx (10" Round)	10AVRxxx, 10MFxxx, A10RCFRxxx	32CDAVxxx, 32CDAVFRxxx, 32CDFLxxx, 32CDFLFRxxx, 32CDLTxxx, 32CDLTFRxxx, 32CDPHxxx, 32CDPHFRxxx (32" Channel Drain)	32CDAVNFxxx, 32CDFLNFxxx, 32CDLTNFxxx, 32CDPHNFxxx
10RCFRxxx, A10RCFRxxx (10" Round)	A10RCFRxxx	32CDAVVxxx, 32CDFLVxxx, 32CDLTVxxx, 32CDPHVxxx (32" Channel Drain)	32CDAVNFxxx, 32CDFLNFVxxx, 32CDLTFRxxx, 32CDPHNFxxx

*See AquaStar Color Chart for Part Ending #s / Color Codes:

100=Clear, 101=White, 102=Black, 103=Light Gray, 104=Blue, 105=Dark Gray, 108=Tan



Be a pool and spa professional! Always follow and understand AquaStar's installation instructions thoroughly. Compliance to the VGB act and related standards does **NOT** stop with installation of the compliant cover. The existing frame/sump must be in good condition, or it should also be replaced; the sump needs to be at least at each model's required depth; and the new screws must securely fasten to the frame.

PLEASE CALL OR VISIT OUR WEBSITE FOR MORE INFORMATION

877-768-2717 +1-805-620-5060 (outside the U.S.) www.aquastarpoolproducts.com